



## PRODUCT CHANGE NOTIFICATION

Date: September 16, 2015  
PCN: PCN LEDIL 108 b

---

**Subject: PCN 108.b - Replacement of assembly component**

Description: As part of our continuous improvement process regarding the quality of our products LEDiL has replaced holder in assembly FCA11151\_NIS83-MX-O-90 from C10498\_ROSE-HLD-N83-WHT to F10355\_ROSE-HLD-E-WHT.

Time line: We will deplete existing stock before making the change

Affected products: FCA11151\_NIS83-MX-O-90

Changes: Product code of FCA11151\_NIS83-MX-O-90 will be changed to **FA11151\_NIS83-MX-O-90**.

This change does not have effect on optical performance or mechanical compatibility of the products.

Contact information: Tero Mäkinen  
LEDIL Oy  
Salorankatu 10  
24240 SALO, FINLAND  
tero.makinen@ledil.com