

PRODUCT CHANGE NOTIFICATION

Date: September 18, 2015 PCN: PCN LEDIL 109 b

Subject: PCN 109.b - Change of assembly instructions

Description: As part of our continuous improvement process regarding

the quality of our products LEDiL has updated C13806_MIRELLA-XW-PF

assembly instructions to include glue for fastening.

Time line: This change is valid immediately

Affected products: C13806_MIRELLA-XW-PF

Included in assemblies: CN14209 MIRELLA-XW-PF-VER013

CN14211_MIRELLA-XW-CL-PF-VER013 CN14212_MIRELLA-XW-DL-PF-VER013

CN14568_MIRELLA-XW-DL-PF CN14572_MIRELLA-XW-CL-PF CN14576_MIRELLA-XW-RZL-PF CN14755_MIRELLA-XW-PF-XTM

Changes: C13806_MIRELLA-XW-PF assembly instructions has been updated to

include glue for fastening. This change does not have effect on optical

performance of the products.

Contact information: Tero Mäkinen

LEDIL Oy Salorankatu 10

24240 SALO, FINLAND tero.makinen@ledil.com